




SAFETY CERTIFICATE

The school building of Shivalika Public School, Village Palhuni, PO Malnu, Tehsil Palampur, Distt. Kangra H.P was inspected by Junior Engineer of Khera-I Section on dated 08.02.2024. As per the report of the Junior Engineer, this building has neither been designed nor been supervised by this department and no earthquake resistant provisions have been adopted for the design of this building & no structural drawings duly approved by the competent Govt. certified Engineer were produced at the time of inspection. So this structure is a non-engineered structure. Hence, the structural safety of this building cannot be ensured specifically from the earthquake resistant point of view. This department will not be responsible for any type of loss of life and property etc., if this structure fails under any circumstances. However, as per the visual inspection of the building this time it has been found safe. No Officer/Official of this office will plead in any Hon'ble court of law in case of dispute and this certificate is valid only upto 31.03.2025.

Note: This certificate is valid for the year 2024-25 or till any addition or substantial change in loading of the building structure is made.


J.E.


Assistant Engineer,
HP PWD Sub-Division,
Bhawarna.


Executive Engineer,
Bhawarna Division,
HP. PWD, Bhawarna.